

Rust Inhibitor Process

1. Grind off excess rust / scale
2. Prep / clean
3. Apply rust inhibitor, allow 24 hours to cure (but can be walked on within a couple hours)
4. Paint

The rust inhibitor we apply reacts with the metal and converts the iron oxide (rust) to stabilized magnetite. It also acts as a sealer and primer

